

Release Note NBSW 3.3.2

Project Name: NetBox Software (NBSW)

Abstract:

This document is the Release Note for NetBox Software 3.3.2 to be used for the NB1310. It informs on new functionality, corrections and known issues of the current version of NetBox Software.

Keywords:

NetModule, Product Management, NBSW, Release Note

Document Control:

Document:	Version	1.0
	File	release_note_nbsw_3.3.2.4637.docx
	Status	Valid
Creation:	Role	Name
	Author	Samuel Hess
	Co-Author(en)	
Approval:	Role	Name
	EVP Products	Thomas Siegrist

Contents

Release Information.....	3
New Functionality in this Release	4
Resolved Issues.....	5
Known Issues.....	6
Pitfalls.....	7

Release Information

NetBox Software:

Version: **3.3.2.4637**

Date: **January 12, 2010**

Supported Hardware

Name and version NetBox Wireless Router NB1310 HW V1.0

New Functionality in this Release

This is the initial NetBox Software Release for the NetBox NB1310. It offers the same functionality as the NetBox Software Release 3.3.2.2286 offers on the NB2xxx models.

For more information see http://www.netmodule.com/store/support/netbox/netbox_manual_e.pdf.

Case-#	Description
18739	OpenVPN Bridge The NB1310 can operate OpenVPN in bridging mode.
18739	OpenVPN Server The NB1310 can operate OpenVPN in server mode.

Resolved Issues

The following issues have been resolved:

Case-#	Description
18611	Configuration Parameters Leading spaces in configuration parameters cannot harm the NetBox any more
18607 18530	Web Manager via HTTPS - HTTPS is now working as expected - The Software Update in HTTPS mode is disabled due to an unsolved problem
18685	Time Synchronisation Disabling NTP time synchronisation is working now
18635	Manual Network Selection Any network (whether available or not) can now be configured
18805 18806	Connection Supervision Monitoring of connection establishment did not work
18753	Web CLI Allow multiple set commands using cli.php
18825	Wrong Configuration after Software Update Wrong profile switch condition after software update has been fixed

Known Issues

Items listed are minor problems known at the time of release. These issues might be resolved in a later version.

Case-#	Description
18550	OpenVPN Expert Mode The first attempt to load a file in the OpenVPN Expert Mode fails. However, the second attempt is successful.
18304	IPsec Tunnels IPsec Tunnels with Peer Address 0.0.0.0 do not work.

See also general Known Issues of the respective NetBox Software Release for the NB2xxx platform:
http://www.netmodule.com/store/support/netbox/Release_note_NBSW_3.3.2.2286.pdf

Pitfalls

Items listed as pitfalls are potential problems that may arise due to the design of the environment NetBox interacts with or components that are used by NetBox. No fixes are planned.

Case-#	Description
-	The NetBox does not recognize SIM card insertion or change while it is running. Therefore, a power cycle of the NetBox is required after any SIM card insertion or change.

See also general Pitfalls of the respective NetBox Software Release for the NB2xxx platform:
http://www.netmodule.com/store/support/netbox/Release_note_NBSW_3.3.2.2286.pdf

Changes:

Version	Date	Name	Reason
1.0	13.01.2010	she	Release

Copyright © 1998 - 2010 NetModule AG; All Rights reserved

This document contains proprietary information of NetModule AG. No part of the work described herein may be reproduced. Reverse engineering of the hardware or software is prohibited and is protected by patent law.

This material or any portion of it may not be copied in any form or by any means, stored in a retrieval system, adopted or transmitted in any form or by any means (electronic, mechanical, photographic, graphic, optic or otherwise), or translated in any language or computer language without the prior written permission of NetModule AG.

The information in this document is subject to change without notice. NetModule AG makes no representation or warranties with respect to the contents herein and shall not be responsible for any loss or damage caused to the user by the direct or indirect use of this information. This document may contain information about third party products or processes. This third party information is out of influence of NetModule AG therefore NetModule AG shall not be responsible for the correctness or legitimacy of this information. If you find any problems in the documentation, please report them in writing by email to info@netmodule.com at NetModule AG.

While due care has been taken to deliver accurate documentation, NetModule AG does not warrant that this document is error-free.

“NetModule AG” and “NetBox Wireless Router” are trademarks and the NetModule logo is a service mark of NetModule AG.

All other products or company names mentioned herein are used for identification purposes only, and may be trademarks or registered trademarks of their respective owners.

The following description of software, hardware or process of NetModule AG or other third party provider may be included with your product and will be subject to the software, hardware or other license agreement.

NetModule AG is located at

Meriedweg 11
 CH-3172 Niederwangen
 Switzerland

info@netmodule.com

Tel +41 31 985 25 10

Fax +41 31 985 25 11

For more information about NetModule AG, visit the NetModule web site at: www.netmodule.com